

Errata Sheet

Device Vehicle Link 3100
Part-No 0 273 600 023 R5
Firmware Version 5.11.1

Overview

This Errata Sheet describes a product deviation with respect to the user documentation listed below:

Safety Data Sheet 1 689 989 323 | 2018-01-20

Deviation of technical data

Deviation 1 - Quiescent current

Quiescent current of the device has typical value of 1.015mA instead of <1mA as declared in above referenced user documentation. The reason is an introduced feature to measure the battery voltage of the vehicle during parking phases.

Workaround

None

Impact to the user

Negligible. As already stated in above reference user documentation, we recommend to unplug the VL 3100 from the OBD2 interface if the vehicle is not used for an extended period of time.

00		20190509	sco1fh						CS/ENC	
Ind.	Change	YYYYMMDD	Created	Checked	Releas.	BWN	Resp. Dept.	Add. Info		
Lang.	MNR	Mat.meets	Syst.	Doc.type	DP	Ind.			Format	Sheet
en		N 2580-1	DOC	DB	000	00			A4	1/1